

00862.022315



C of C \$
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

Mitsuru HIURA)
Application No.: 09/915,325) Examiner: A. E. Dudding
Filed: July 27, 2001) Group Art Unit: 2853
For: EXPOSURE APPARATUS AND DEVICE) August 23, 2005
MANUFACTURING METHOD USING THE SAME :
U.S. Patent No. 6,891,175 B2 :
Issued: May 10, 2005 :
:

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
Attention: Certificate of Correction Branch

Certificate
AUG 26 2005
of Correction

**REQUEST FOR
CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

Patentee requests that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of U.S. Patent and Trademark Office mistakes and mistakes of a minor nature which are not the fault of the Patent and Trademark Office.

08/24/2005 JBALINAN 00000043 6891175

01 FC:1811

100.00 0P

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. Office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,



Attorney for Patentee
Steven E. Warner
Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
SEW/eab

DC_MAIN 212591v1

AUG 26 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,891,175 B2

DATED : May 10, 2005

INVENTOR(S): Mitsuru HIURA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 50, the first occurrence of "a" should be deleted.

COLUMN 6:

Line 38, "he" should read -- the --.

COLUMN 8:

Line 33, "(mm/sec):" should read -- (mm/sec²): --.

COLUMN 11:

Line 9, "(10," should read -- (10), --.

Line 26, "become" should read -- becomes --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,891,175 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

No. of add'l. copies
@ 30¢ per page



AUG 26 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,891,175 B2

DATED : May 10, 2005

INVENTOR(S): Mitsuru HIURA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12:

Line 51, "go" should read -- g() --.

Line 52, "go" should read -- g() --.

COLUMN 16:

Line 1, "a" should be deleted.

COLUMN 17:

Line 10, "acceleration" should read -- deceleration --.

Line 59, "VP=" should read -- Vp= --.

COLUMN 18:

Line 22, "length on" should read -- length of --.

Line 61, "size; Vt." should read -- size: Vt. --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,891,175 B2

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile
FORM PTO 1050 (REV. 3.82)

No. of add'l. copies
@ 30¢ per page

